



Item Description

GENERAL SPECIFICATIONS

Display mode: LCD displaying.

Max. indication: 3999 (3 3/4) , auto polarity indication

Measuring method: Dual integral A/D conversion.

Sampling rate: Approx. 3times/second

Over range indication: " OL" displays

Low battery : The " " displays.

Operating environment: (0 ~ 40)°C , humidity<75%RH.

Power: 9V battery (NEDA1604/6F22 or same model)

Dimension: 175mm×93mm×55mm .

Weight: approx 400g (include 9V battery).

Environment temperature: (23±5)°C

Relative humidity: <75%RH

Accessories: Operation manual, holster, gift box, TP01 thermocouple, test leads , 9V battery.

More details please refer to the Manual !